EA

A. 30239

# **OCULAR INSPECTION CHECKLIST**

Α.	GENERAL INFORMATION	
1.	Street Address of the School: 100-198 Calle Feder-co Garcia	
_	City: Fajor do State: P. R Zip: 00738	
2.	School Name: Ramon Quirones lacheco	
3.	Date of inspection: 1/10 /2020	
4.	Inspector's Name: Waldeman Nieves	
B.	BUILDING SITE INSPECTION	
5.	Utility Service Safety:	
detected	RTANT–Immediately following an earthquake, check the entire property, especially near appliances, for the smell of gas. If gased, turn off the gas at the meter where it enters the house. Locate and repair leaks before turning gas back on. If the gas odd the gas has been shut off, vacate the building and contact the gas utility company immediately.	s odor is or persists
IMPOR <sup>*</sup> valve, e	RTANT–Before entering a damaged, vacant building verify that gas is off. Check the gas meter for damage and position of ma either a manual valve or a seismically-activated gas shut-off valve. Do not enter the building if gas odor is detected.	ain gas
	a. Odor of natural gas leakage?    YES    NO    b. Downed powerlines?    YES    NO	
6.	Surrounding topography: (@check one)  Flat  Gently sloping (easily walkable)  Steeply sloping (difficult or impossible to walk in some areas)	
7.	Building pad: (Incheck one)  Flat  Terraced or multilevel  Gently sloping (less than 4-foot ground surface elevation difference across house)  Steeply sloping (greater than 4-foot ground surface elevation difference across house)	
8.	Geotechnical Issues: (if yes, provide description and photos)	NO
	a. New cracks in the ground?	X
	b. Signs of fresh cracking in or movement of hardscape?  c. Signs of fresh cracking in or movement of retaining walls?	X
	d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?	x
	e. Evidence of sand boils or other fresh-appearing deposits of sand or mud?	*
	f. Unusual slumping, rising, or bulging of the ground surface?	1
	g. Evidence of rock falls or slope instability above site?	X
	h. Ground movement or wet areas indicating possible broken underground utility lines?	X
	i. Other phenomena (e.g., septic tanks surfacing, differential settlement, ground consolidation)?	X

B.	BUILDING SITE INSPECTION (continued)	YES NO
9.	Evidence of earthquake-induced permanent ground deformati property?	on in the immediate vicinity of the
C.	GENERAL BUILDING INFORMATION	
10.	Safety Assessment Tag: (©check one) None (others):	Green Yellow Red
11.	a) Year of original construction (best estimate): 1901 b) Total square footage (best estimate): 28, 118 SF	YES NO
12.	Have any repairs, modifications, or demolition been performe	d since the earthquake?
13.	Building configuration:  a. Single story  b. Combination one and two story  c. Full two story  d. Three story  e. Split level  f. Typical  g. Other, describe  Exterior wall finish:	Sill bolting:  a. Structure bolted to foundation b. Structure not bolted to foundation c. Don't know  Roof configuration:  a. Gable b. Hip C. Flat or very low slope d. Shed
	a. Stucco b. Panel siding c. Metal siding d. Masonry veneer e. Other, describe	e. Other, describe  Roof covering:  a. Asphaltic membrane  b. Wood shingle or shake  c. Concrete
15.	Foundation configuration:  a. Slab-on-grade  b. Crawlspace without cripple walls  c. Crawlspace with cripple walls  d. Exposed piers or posts  e. Typical  f. Metal  g. Other, describe	d. Metal e. Elastomeric f. Other, describe

D.	EXTERIOR BUILDING INSPECTION			7
19	. General: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or building off foundation?	The state of the s	K	
	b. Obvious lean in any story?	paradololina Gilipedikus		
20.	Exterior walls: (if yes, provide description and photos)			
	a. Fresh cracking at corners of door and window openings?	a internal	K	
	b. Fresh cracking at building corners?			
	c. Door or window openings racked out of square?	· · · · · · · · · · · · · · · · · · ·	X	107 hans
	d. Broken glass in windows or doors?	Company of the Compan	X	
	e. Wall leaning?		R	
	f. Bulging or delamination of stucco?		<b>1</b>	
	g. Pattern of cracking that extends from the ground surface, through foundation, and wall?			
	h. Evidence of recent relative movement at mudsill line?	27744752	A	
	i At locations where the exterior stucco is continuous from the framing down over the		X	
	foundation, is there cracking of stucco along the mudsill level accompanied by indications			
	of permanent displacement (sliding) of the building relative to the foundation?			
	j. Collapse, partial collapse, or separation of masonry veneer?		4	
	k. Severe cracking, separations, or offsets at building irregularities?	TOWN TOWN	Z	SCOOLS SALES
21.	Foundation: (if yes, provide description and photos)	patitationeg		
	a. Fresh cracking of exposed perimeter foundation?			
	b. Relative movement between slab and footing in "two-pour" slab-on-grade foundations?			
	c. Ask homeowner if any earthquake retrofits have been done to the home?			
	If Y describe:		W. W. WALLES	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	d. If the answer to c is Y, were bolts added to connect the home to the foundation?		in the second	assessus.
	e. If the answer to c is Y, were plywood or sheathing added to any cripple walls under the home?			emanasa A
				J

D.	EXTERIOR BUILDING INSPECTION (continued)			(
	22. Kitchen Hook (if yes, provide description and photos)	YES	NO	N/A
	a. Present on external wall?			
	b. Present at internal location?			
	c. Collapse or partial collapse?			
	d. Visible damage or cracking?	1.		
	e. Visible tilting or separation from building?			
	f. Shifted or loose and displaced			
	g. Deterioration or deformation			
	El lomedor no se inspectoro ya que no hobian claves para entre al mismo.			
23.	Roof: (if yes, provide description and photos)			
	a. Shifted or dislodged or concrete damage?		X	
	b. Impact damage to roof from falling object?		X	
	c. Displaced rooftop HVAC units?			
	d. Significantly sagging roof ridgelines?		×	
	e. Signs of movement between rafter tails and wall finishes at eaves?		X	
	f Buckled/dislodged flashing or tearing of roof membrane, roof/wall intersections in split			
	level buildings, additions, or other building irregularities?			
	g. Tearing of roof membrane or deck waterproofing at re-entrant corners?			
	h. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of rooftop		X	
	mechanical equipment?			
	i. Shifting of or damage to solar panels?			×
				7

D.	EXTERIOR BUILDING INSPECTION (continued)						
24.	Attached or abutting improvements: (if yes, provide description and photos)	YES	NO	N/A			
	a. Collapse, partial collapse, or separation of attached porches, carports, Gazebos, or awnings?	_					
	b. Evidence of recent settlement or displacement of exterior steps, patios,		X				
	or walkways relative to the building?		X				
	c. Signs of movement between building floor and/ or exterior hardscape or retaining						
	wall along the uphill side of hon steeply sloping sites?  d. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of		X				
	air conditioning condenser unit(s)?						
0.5							
25.	Independent exterior improvements: (if yes, provide description and photos)			X			
	a. Damaged detached gazebo?		X	$\overline{\Box}$			
	b. Damage to fences / privacy walls?		λ				
	c. Damage to retaining walls?						
	d. Damage to walkway?		X				
	e. Evidence of leakage from water supply lines?		X				
	f. Toppling, shifting, or damage/leakage at fuel connection of propane tanks?		X				
	g. Others damage		X				
E.	INTERIOR INSPECTION						
26.	General information						
	a If interior access not possible, identify reason	finish		11			
	i. Red tag ii. Hazardous materials iii. Hazardous materials iii. Plaster on gypsu	ım lath					
	iii Other hazerdaus condition iii Plaster on wood	lath					
	describe iv. Other, describe	Pluster					
	iv. Other, describe						

E.	INTERIOR INSPECTION (continued)			
27.	Walls: (if yes, provide description and photos)	YES	NO	N/A
	a. Fresh cracking, buckling, spalling, or detachment of interior wall finish at corners of	X		
	door and window openings? En el salon # 13, se doppo el			
	b. Fresh cracking of wall finishes at wall corners or wall/ceiling intersections?	X		
	c. Door or window openings racked out of square?		X	
	d. Wall leaning?		X	
	e. Pattern of cracking that extends from the floor slab through the wall?		X	
	f. Movement or sliding of walls relative to the floor?		X	
	g. Severe cracking, separations, or offsets at building irregularities?		X	
	h. Doors damaged, difficult to operate, or inoperable?		X	
	i. Windows damaged, difficult to operate, or inoperable?		X	
28.	Ceilings: (if yes, provide description and photos)			
	a. Collapse of ceiling finish?	X		
	b. Fresh cracking of ceiling finishes, especially at re-entrant corners; cracks along corner	X		
	bead at stairwell openings; cracking or tearing of finishes at ceiling/wall juncture; or multiple	í		
	"nail pops"?			
	c. Damage to ceiling finishes in vicinity of corridors or commons places?		X	
	d. Separations or cracks in ceiling finishes at split-levels, re-entrant corners,		R	
	additions, appendages, or other building discontinuities?			
	e. Water damage or evidence of recent leakage from plumbing lines or roofing?		1	

2018 2018 2018	INTERIOR INSPECTION (continued)			
29.	Floors: (if yes, provide description and photos)	YES	NO	N/A
	a. Evidence of recent sloping, sagging, settlement or displacement of floors?	Production of the Control of the Con	X	pagarena
	b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes?			
	c. Significant sagging or unusual bounciness of floors frames?	economy.	X	
	d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions,			
	appendages, or other building discontinuities?		on-constitution of the constitution of the con	мжения
	e. Signs of movement between floor and exterior hardscape or retaining wall along	ensilhere Lee	A	
	the uphill side of homes on steeply sloping sites?	processors and	<b>171</b>	paumos.
	f. A pattern of fresh cracks, gaps, or joint separations in floor finishes?			
	g. Impact damage to floor finishes from falling contents?		Λ	<u>L_</u>
		·	P4-2731143	
30.	Mechanical systems: (if yes, provide description and photos)	energy.	, mineratura	X
	<ul><li>a. Displaced connection of appliance flues connected to chimneys?</li><li>b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue</li></ul>		ι <u>∨</u>	
			X	
	connection or damage/leakage at gas line or electrical connection of water heater?		5	**************************************
	c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line,			Locketinis
	and condensate drain connection of furnace or air conditioning fan-coil unit?		Z	
	d. Damage to gas line of gas stoves or gas fueled clothes dryers?		(2000)	
	e. Damage to toilets?		X	
	f. Decreased or restricted water pressure at appliances, faucets, or toilets?		X	
	g. Toppling or shifting of free-standing wood stove and/or flue?	essentation.	<u> </u>	
	h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank?	demonstrates		
	i. Other Damage in the dining room			
	j. Damage near the gas tank		M	
		ACTORINA		anoma

	INTERIOR INSPECTION (continued)			
31.	Architectural woodwork and special finishes: (if yes, provide description and photos)	YES	NO	N/A
	a. Shifting of or damage to kitchen or bathroom cabinetry?			
	b. Impact damage to countertops from falling objects?	- Aller and Alle	CAMPAGE AND A	
	c. Cracking of ceramic tile in showers or tub/shower enclosures consistent with	erromana.	programme de	
	earthquake damage to adjacent wall finishes?			
	CONTINGENTINSPECTIONS	ini Kalanda (((k. p. p.) K. p.		
		YES	NO	N/A
32.	Retaining Tank Wall damage?	A CONTRACTOR OF THE PARTY OF TH	Processing of the Control of the Con	
33.	Water tank or other field subterranean structure		ATTERNACE A	)

ì.	RECOMENDACIÓN AL SECRETARIO		
	Departamento de Educación Dr. Eligio Hernández Pérez Secretario de Educación		
	Hora de Entrada a Inspección:  11:00 Am  Escuela:  Ramon Queones Pacloco  Municipio:  Fajardo	Hora de Salida de Inspección: Código: Fecha de Inspección:	12:50 30239 1/10/2020
3	Abrir Escuela (Verde)  Abrir Parcialmente la Escuela (Amarillo)  No Abrir la Escuela (Rojo)		
	Comentarios: En el solon #59#6 se desprendró el en el solon #5 se desprendró el ventana. En el solon #20 existe esta por desprendrese. Ne se prodo y a que no hobían lloves en la econ covacter de vigencia el emperor la seguridad de los estados	accesor al scula. Se vinetado en las	emperatedo que
	Tus. W-1Jemes Nieves Pivera Nombre (Letra de Molde)  Was el P  Firma	4269 #Licencia	SOLIO LIC. 2426

				· ·
				**************************************