

Facility Evaluation (Site) Form for: Jose Gualberto Padilla |Codigo: 10348

Inspector(s) Name:

MZ-06

Inspection Date:

Tue Oct 31 2017

Inspection Time:

12:00:31 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Jose Gualberto Padilla

School Code:

10348

Latitude:

18.46262648

Longitude:

-66.73030549

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

No issues.

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Water cisterns existing but not working.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

A/C units cannot be check because no power at school.

Access:

- Safe Access to Buildings: **Yes**

Comments:

No issues.

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

At south side of school a falling tree broke fence opening a gap that allow students and people to get in/out of school. Fence in this area completely destroyed.

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Moderate**

Comments:

1) Two electrical power lines down inside school (see sketch). 2)At court two light poles down and one basketball board down.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

On fire suppression system tank is empty.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**

Comments:

No issues.

Additional Comments:

Open catch basin without protection at yard.

Findings:

1) Two electrical power lines down inside school (see sketch). 2) At court two light poles down and one basketball board and pole down. 3) Open catch basin without protection at yard. 4) At south side of school a falling tree broke fence opening a gap that allow students and people to get in/out of school. Fence in this area completely destroyed. 5) Tree debris trunks on front of building 5.

Recommendations:

1) Call power authorities to removal of electrical cables (refer to sketch). 2) Removal of broken light poles and basketball board (refer to sketch). 3) Barricade open catch basin. 4) Removal of damaged fence and rebuild with a new one. Barricade area until new fence is build. 5) Removal of tree debris trunk in front of building 5.
