

Facility Evaluation (Site) Form for: Su Federico Degetau |Codigo: 10546

Inspector(s) Name:

SJ-14

Inspection Date:

Mon Oct 23 2017

Inspection Time:

12:29:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Su Federico Degetau

School Code:

10546

Latitude:

18.44567864

Longitude:

-66.66479811

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

one cistern works out of tree, 7,800 W power generator donated by CIPAP.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Fence partially collapsed behind building 6.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Severe**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Partially collapsed aluminum ceiling behind building 6 (falling hazard).

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Some screens are missing from lunch room windows.

Buildings:

- Building 6: **Yellow - Restricted Use**

Comments:

Behind building number 6 there's a aluminum ceiling that's partially collapsed and may all any time. Fence behind building 6 has partially collapsed due o a fallen tree.

Additional Comments:

Barricades are needed behind building 6.

Findings:

1. There's a partially collapsed aluminum roof behind building 6 that possesses a falling hazard. 2. Fence behind bldg. 6 collapsed due to a fallen tree. 3. Bldg 8, 9 does not have water due to broken pipe.

Recommendations:

1. Barricade the area behind building 6 2. Water pipe must be fixed.
