

# Facility Evaluation (Site) Form for: Fernando Suria Chavez |Codigo: 10702

---

**Inspector(s) Name:**

SJ12 - Lebron, Castro, Gimenez

**Inspection Date:**

Mon Oct 23 2017

**Inspection Time:**

07:47:22 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Fernando Suria Chavez

**School Code:**

10702

**Latitude:**

18.45165677

**Longitude:**

-66.53829556

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

Facility was not flooded

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

1- Fallen communication feeding line. 2- Water cistern pump does not work.

---

## Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

### Comments:

Mechanical ventilation units on roof damaged by wind.

---

## Access:

- Safe Access to Buildings: **Yes**

### Comments:

---

## Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

### Comments:

---

## Overall Areas:

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

### Comments:

1-Building 3 classrooms debris limits pedestrian access. 2- Hanging aluminum sheet (brise soleil) in west facade.

---

## Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### Comments:

No electricity available to mechanical equipment.

---

## Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

- Building 3: **Yellow - Restricted Use**

**Comments:**

Building 1: acoustic ceiling panels fallen. Replace glass window jalousie. Building 2: Repair end roof paneling. Replace acoustical ceiling. Building 3: Remove debris from sidewalk. Water leaks filtration.

---

**Additional Comments:**

1- Green house lab structure partial collapse. 2- Collapsed basketball court roof need to be barricaded until it is removed from site.

---

**Findings:**

1. Basketball court roof collapsed. 2. In basketball court, parking area, and in the left side of the school, there is debris and fallen trees. 3. Collapsed roof area in Building #2. 4. Two classrooms (Bldg 3) have a piece of the roof collapsed causing several leaks.

---

**Recommendations:**

1. Barricade basketball court area until roof can be removed or repaired. 2. Barricade area where there are debris and fallen trees until they are removed. 3. Collapsed roof area in Building #2 needs to be barricaded until debris are removed. 4. Two classrooms (Bldg 3) need to be restricted until they can be repaired.

---