

Facility Evaluation (Site) Form for: Dr Francisco Vazquez |Codigo: 10835

Inspector(s) Name:

CSA Group SJ-13

Inspection Date:

Mon Oct 23 2017

Inspection Time:

11:00:45 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Dr Francisco Vazquez

School Code:

10835

Latitude:

18.4167366

Longitude:

-66.56947677

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

No building are flooded

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Cistern not working (cistern don't have water)

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Opened Windows

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Trees damaged the fences, barbed wires hazards

Overall Areas:

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Moderate**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Severe**

Comments:

Barbed wires, fallen trees and highly damaged fences. Also a electric pile may fall on building #8.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Operational exhaust fan not installed.

Buildings:

- Building 1: **Yellow - Restricted Use**

- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

Comments:

Green if: Fix electrical pipe on bulding #1, Moderated damaged at canopy (broken metal decks) on building #4, broken metal deck at canopy on building #5, electrical pile on roof may fall on building #8. Recommendations: Contact an electricist and remove the broken metal decks.

Additional Comments:

Green if: Remove damaged trees in parking areas. Remove all the downed power lines and electrical hazards. Fix perimeter fences and hazardous barbed wires.

Findings:

1. Basketball court roof collapsed. 2. In basketball court, parking area, and in the left side of the school, there is debris and fallen trees. 3. Collapsed roof area in Building #2. 4. Two classrooms (Bldg 3) has a piece of the roof collapsed causing several leaks.

Recommendations:

1. Electrical Assessment is recommended to fix electrical pipe and wires on roof 2. Remove broken metal desks (debris) 3. Fix and/or barricade perimeter fence
