

Facility Evaluation (Site) Form for: Laurentino Estrella Colon |Codigo: 10959

Inspector(s) Name:

MZ06

Inspection Date:

Mon Oct 30 2017

Inspection Time:

10:50:33 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Laurentino Estrella Colon

School Code:

10959

Latitude:

18.48503002

Longitude:

-66.84770606

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Director requested to increase drain size prior hurricane avoiding flooding

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **Yes**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Three cisterns prior Maria. Only one remains at the kitchen. 2 other cisterns disappeared or missing.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

Comments:

Operational windows in all rooms. AC units working prior Maria. Ac units in building 2 and tech room are not working now.

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Damaged in two locations behind building and north side of parking; and east side.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Cable low at east side.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Cafeteria was used to cook for refugees.

Buildings:

- Building 1: **Green - Inspected**

- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**

Comments:

Additional Comments:

Findings:

Power cable low at east side. One of three cisterns operational. Gutters damaged at the basketball court. School was used as shelter and mass feeding.

Recommendations:

Provide and install missing cisterns at bathrooms. Install safety tape or fence at low power cable and damaged fence sections until can be repaired. Electrician evaluation is recommended.
