

# Facility Evaluation (Site) Form for: Ralph W Emerson |Codigo: 10967

---

**Inspector(s) Name:**

Angel Ramirez, Edmanuel Lorenzo

**Inspection Date:**

Mon Oct 30 2017

**Inspection Time:**

09:28:06 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Ralph W Emerson

**School Code:**

10967

**Latitude:**

18.47218464

**Longitude:**

-66.87327002

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Filtration in classrooms b 205, outside of classroom b 209, b 106 has mold growth and b 105 has water filtration

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **Yes**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Generator is not in function because of panel damage.

---

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

**Comments:**

---

## **Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

---

## **Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

---

## **Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

---

## **Buildings:**

**Comments:**

---

## **Additional Comments:**

---

**Findings:**

1. Water filtration in classrooms b 106, 103, outside 209 and 205. Classroom b 106 has mold growth.

---

**Recommendations:**

1. Restrict access to classroom b 106; 2. Electrical evaluation is recommended.

---