Facility Evaluation (Site) Form for: Antonio Reyes | Codigo: 11023

Inspector(s) Name: Angel Ramirez, Edmanuel Lorenzo **Inspection Date:** Mon Oct 30 2017 **Inspection Time:** 11:30:18 GMT-0500 (Central Daylight Time) Type of Facility: escuela **School Name:** Antonio Reyes **School Code:** 11023 Latitude: 18.45143366 Longitude: -66.85403204 **Building Contact: Number of Buildings: General:** • Facility Area Flooded: No • One or More Buildings Flooded: No

Services:

Potable Water Service: NoPotable Water Cistern: No

• Other Water Damage in Facility: No

• Sewer Service: No

Comments:

Septic Tank Available: YesElectrical Power Service: Yes

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

 Adequate Classroom Ventilation: Yes • AC System Operating: Yes **Comments:**

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

Comments:

The fence is down in 3 sections because of fallen trees.

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

Comments:

There is a energized power line to close to the ground

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1., The fence is down in 3 sections because of fallen trees; 2. An energized power line is too close to the ground.

Recommendations:

1. The areas were the fence is down must be fixed or barricaded; 2. The power line must be out of reach of students.