

Facility Evaluation (Site) Form for: Su Toribio Rivera |Codigo: 11312

Inspector(s) Name:

Jonathan Velazquez, Chrystiaan Gonzalez

Inspection Date:

Mon Oct 30 2017

Inspection Time:

07:03:19 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Su Toribio Rivera

School Code:

11312

Latitude:

18.30375567

Longitude:

-66.55532093

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

kindergarten BLD #2 roof collapse

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

lunchroom cistern is the only one working other cisterns are broken

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

3 points of the perimeter fence are damaged (hit by trees)

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Moderate**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Moderate**

Comments:

Downed power lines (near BLD #5 and BLD #10) and recreational canopy is highly damaged it may fall. Electric post broken it may fall cables are holding it. Trees/debris in recreational area.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Red - Unsafe**

- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Yellow - Restricted Use**
- Building 6: **Yellow - Restricted Use**
- Building 7: **Yellow - Restricted Use**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

Comments:

needs general clean up on BLD (#5,#6,#7)

Additional Comments:

Kindergarten classroom (BLD #2) is already relocated

Findings:

1. kindergarten roof collapsed 2. Perimeter fence damage(3 points) 3. Downed power lines 4. Electric post damaged
5.Trees/debris in recreational area 6. fungus on bld #5

Recommendations:

1. Barricade area to restrict access to BLD #2 2. Fix perimeter fence damages 3. Relocate downed power lines 4. Contact electrician to repair downed electric post 5. Remove debris/trees 6. General clean up
