

# Facility Evaluation (Site) Form for: Clemente Ramirez De Arellano |Codigo: 12153

---

**Inspector(s) Name:**

SJ-11

**Inspection Date:**

Mon Oct 23 2017

**Inspection Time:**

08:28:26 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Clemente Ramirez De Arellano

**School Code:**

12153

**Latitude:**

18.42935349

**Longitude:**

-66.44563869

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Ceiling water infiltration

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

communication cable lines are torn down.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

Repair exhaust fan.

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Red - Unsafe**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**

- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Yellow - Restricted Use**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

**Comments:**

Bldg 3 replace metal ceiling. Bldg 8 repair pvc pipes and water infiltration coming down on electrical panel.

---

**Additional Comments:**

---

**Findings:**

1. Bldg 3: torn ceiling. 2. Bldg 8: water infiltration on electrical panel.

---

**Recommendations:**

1. Bldg 3: Do not use classroom; relocate students. 2. Bldg 8: Do not use classroom; relocate students.

---