

Facility Evaluation (Site) Form for: Antonio Velez Alvarado |Codigo: 12187

Inspector(s) Name:

#3 Luis R. Estates / #9 Remi A. Torres

Inspection Date:

Tue Oct 31 2017

Inspection Time:

09:00:29 GMT-0500 (Central Daylight Time)

Type of Facility:

comm_shelter

School Name:

Antonio Velez Alvarado

School Code:

12187

Latitude:

18.43485918

Longitude:

-66.4659751

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

None of the areas were flooded

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

The school don't have potable water cisterns. The school doesn't have a generator.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Can't be check no power yet

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Damaged fence behind lunch room, near the kinder and 1st grade buildings.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Damaged fences and debris trees that need to be restricted. A basketball court near the school have a falling zinc planks. The basketball is not property of the school. School placed debris in a corner and a private company is supposed to picked up soon. A electrical pole fall down in the baseball court.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

No power yet, storage is not flooded.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**

Comments:

Additional Comments:

The school's roof were sealed last semester

Findings:

The school don't have potable water cisterns. The school doesn't have a generator. Damaged fences, debris of trees and branches.

Recommendations:

The school need potable water cisterns, also need generator. The damaged fences and debris of trees and branches need to be restrict, and be removed and repair.
