

# Facility Evaluation (Site) Form for: Dr Pedro Albizu Campos | Codigo: 12872

---

**Inspector(s) Name:**

Calderon, Santiago

**Inspection Date:**

Tue Oct 31 2017

**Inspection Time:**

11:45:02 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Dr Pedro Albizu Campos

**School Code:**

12872

**Latitude:**

18.46848906

**Longitude:**

-66.93910224

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Water leaks through broken a/c. School cleaned classroom and fixed it.

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **Yes**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Storm broke and damaged water cisterns

---

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

### **Comments:**

Only the 8th grade science's classroom (2nd level) with damaged ac.

---

## **Access:**

- Safe Access to Buildings: **Yes**

### **Comments:**

None

---

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

### **Comments:**

Fence damaged and fallen behind lunchroom and backside of school due to fallen trees

---

## **Overall Areas:**

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

### **Comments:**

Basketball court with loose metal sheet wall hanging, damaged zinc roof with a hole, lighting fixtures broken, and debris scattered through all school outside yard

---

## **Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### **Comments:**

None

---

## **Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

**Comments:**

Bldg1- main bldg, bldg2- basketball court

---

**Additional Comments:**

School contacted public buildings to pick up debris in the next days. School also restricted access through main gate and limited all activities in main building, restricting access to basketball court building

---

**Findings:**

Damaged roof in janitors decommission 's storage. Basketball court is damaged with loose metal sheet walls, lifted roof and perforated roof, damaged lighting fixtures. Huge amounts of debris piled up in several parts of school. Damaged and fallen fences .

---

**Recommendations:**

Fix janitors decommission storage's roof, repair basketball court's roof and walls, and lighting fixtures. Replace damaged fence. Pick up debris immediately

---