Facility Evaluation (Site) Form for: Ramon De Jesus Sierra | Codigo: 15917

Inspector(s) Name: Yendelíz Martínez/ Wilson Torres **Inspection Date:** Mon Oct 30 2017 **Inspection Time:** 16:16:19 GMT-0500 (Central Daylight Time) **Type of Facility:** escuela **School Name:** Ramon De Jesus Sierra **School Code:** 15917 Latitude: 18.29765677 Longitude: -66.88002334 **Building Contact:** Number of Buildings:

General:

- Facility Area Flooded: No
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Services:

- Potable Water Service: Yes
- Potable Water Cistern: Yes
- Sewer Service: Yes
- Septic Tank Available: No
- Electrical Power Service: Yes
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

1 cistern available.

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: Yes

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Severe

Comments:

Erosion and ground movement at school building side.

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Moderate
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Moderate
- Electrical or Power Line Hazards: Minor/None

Comments:

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: No
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

Comments:

Buildings:

- Building 1: Green Inspected
- Building 2: Green Inspected

Comments:

Additional Comments:

Findings:

1. Erosion and ground movement at school building side; 2. Tension cable near school entrance.

Recommendations:

1. Perform geotechnical evaluation due to erosion and ground movement at school building side; 2. Remove and replace tension cable near entrance.