Facility Evaluation (Site) Form for: Luis F Crespo | Codigo: 17384

Inspector(s) Name: Angel Ramirez, Edmanuel Lorenzo **Inspection Date:** Mon Oct 30 2017 **Inspection Time:** 10:45:28 GMT-0500 (Central Daylight Time) Type of Facility: escuela **School Name:** Luis F Crespo **School Code:** 17384 Latitude: 18.46542592 Longitude: -66.85216245 **Building Contact: Number of Buildings: General:** • Facility Area Flooded: No • One or More Buildings Flooded: No

Services:

• Potable Water Service: **Yes**

• Other Water Damage in Facility: No

• Potable Water Cistern: No

• Sewer Service: Yes

Comments:

• Septic Tank Available: **No**

• Electrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

• Adequate Classroom Ventilation: Yes • AC System Operating: Yes **Comments: Access:** • Safe Access to Buildings: Yes **Comments: Perimeter Fences/Walls:** • Damage to Perimeter or Fence: Minor/None • Damage to Retaining Wall or Slope: Minor/None **Comments: Overall Areas:** • Recreation Area Damage: Minor/None • Parking Area Damage: Minor/None • Falling Hazards in Play Areas: Minor/None • Standing Water in Play Areas: Minor/None • Debris or Tree Hazards: Minor/None • Electrical or Power Line Hazards: Minor/None **Comments:** Lunchroom walkway has water filtration **Lunch Room:** • Cooking Equipment: Yes • Refrigerated or Dry Food Storage: Yes • Operational Exhaust Fan: Yes • Fire Suppression System: Yes • Screens: Yes **Comments:**

Buildings:

Comments:

Additional Comments:

Findings:

1. There is no electrical power; 2. There is a downed power line on the entrance

Recommendations:

1. electrical evaluation is recommended; 2. A generator is recommended and remove and fix the downed power line on entrance.