

Facility Evaluation (Site) Form for: Instituto Tec Recinto De Manati |Codigo: 17392

Inspector(s) Name:

SJ-11

Inspection Date:

Mon Oct 23 2017

Inspection Time:

09:48:19 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Instituto Tec Recinto De Manati

School Code:

17392

Latitude:

18.4326923

Longitude:

-66.47237708

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

Bldg 1 flooded but school is repairing. Ceiling Water infiltration on buildings.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **No**

Comments:

School do not provide lunchroom.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

On south area no perimeter fence. All around school repair fence.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Communication cable torn down.

Lunch Room:

- Cooking Equipment: **No**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **No**

Comments:

Lunchroom not available

Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Red - Unsafe**

- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Yellow - Restricted Use**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Red - Unsafe**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

Comments:

Bldg 1 flooded but under repair. Bldg 5 metal ceiling torn down. Bldg 8 mold contamination, ceiling grid and partitions walls torn.

Additional Comments:

Findings:

1. Building 2 (library): ceiling collapsed. 2. Building 8: mold contamination observed; ceiling grid and partition walls are torn.

Recommendations:

1. Building 2 (library): do not use library; barricade area. 2. Building 8: do not use building, move students to safer areas.
