

Facility Evaluation (Site) Form for: Superior Vocacional |Codigo: 17558

Inspector(s) Name:

SJ-14

Inspection Date:

Mon Oct 23 2017

Inspection Time:

08:28:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Superior Vocacional

School Code:

17558

Latitude:

18.44187594

Longitude:

-66.67156917

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

Water leaks in most classrooms on the second floor due to clogged roof drains.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

AAA water service intermittent, water cisterns not working, Septic tank is overflowed because sanitary pumps has no power.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Mayor displacement of A/C units on rooftops.

Access:

- Safe Access to Buildings: **No**

Comments:

Access road has much debris on the sides.

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Perimeter fence partially collapsed behind building one and behind lunch room.

Overall Areas:

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Both ceilings of the basketball courts have completely collapsed, garbage awaiting pick up at back of the school.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

The exhaust fan covers flew off, some windows and screens are damaged or missing.

Buildings:

- Building 3: **Yellow - Restricted Use**
- Building 4: **Yellow - Restricted Use**

Comments:

Building 3 has partially collapsed rolling doors and one fully collapsed rolling door. Building 4 has heavy water leaks on the ceilings of infirmary and electronics classrooms, the rooftop access door is fully displaced but available and the A/C consoles are partially displaced.

Additional Comments:

Findings:

1. Bldg #3 has displaced rolling doors and 1 fully collapsed. 2. Bldg #3, 4 has substantial water leak. 3. Both roofs of the basketball court collapsed. 4. Cover of the Exhaust fan in the kitchen was blown away. 5. Perimeter fence collapsed behind bldg #1.

Recommendations:

1. Barricade the area of the rolling door. 2. Clogged roof drains must be cleared of debris. 3. Collapsed basketball ceiling debris must be clear and barricaded. 4. Barricade the perimeter fence area and repair.
