Facility Evaluation (Site) Form for: Daniel Velez Soto | Codigo: 17673

Inspector(s) Name:

Yendelíz Martínez/Wilson Torres

Inspection Date:

Mon Oct 30 2017

Inspection Time:

15:18:48 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Daniel Velez Soto

School Code:

17673

Latitude:

18.29949382

Longitude:

-66.88230079

Building Contact:

Number of Buildings:

General:

- Facility Area Flooded: No
- One or More Buildings Flooded: No
- Other Water Damage in Facility: Yes

Comments:

Sport classroom that is near basketball court has mold.

Services:

- Potable Water Service: Yes
- Potable Water Cistern: Yes
- Sewer Service: Yes
- Septic Tank Available: No
- Electrical Power Service: Yes
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

1 available

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: Yes

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Good

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

Comments:

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

Comments:

Tension cable near school entrance. It has always been there. Sky lights at basketball court blown away by wind.

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: No
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

Comments:

Only dry food for approx. 4 day.

Buildings:

• Building 1: Green - Inspected

Comments:

Additional Comments:

Findings:

1. Sport classroom that is near basketball court has minor mold at ceiling; 2. Tension cable near school entrance. It has always been there; 3.Sky lights at basketball court blown away by wind.

Recommendations:

1. Remove minor mold at sport classroom that is near the basketball court; 2. Electrical evaluation is recommended; 3. Reinstall sky lights at basketball court.