# Facility Evaluation (Site) Form for: Leonardo Valentin Tirado | Codigo: 17764

## Inspector(s) Name: Sj14 **Inspection Date:** Mon Oct 30 2017 **Inspection Time:** 14:08:47 GMT-0500 (Central Daylight Time) Type of Facility: escuela **School Name:** Leonardo Valentin Tirado **School Code:** 17764 Latitude: 18.37216989 Longitude: -66.56558818 **Building Contact: Number of Buildings:**

#### **General:**

• Facility Area Flooded: No

• One or More Buildings Flooded: No

• Other Water Damage in Facility: Yes

#### **Comments:**

Due to roof infiltration

## **Services:**

Potable Water Service: NoPotable Water Cistern: Yes

• Sewer Service: Yes

Septic Tank Available: No
Electrical Power Service: No
Generator Available: Yes

• Gas (LP) Storage Tank Intact: Yes

### **Comments:**

Generator is not working

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

#### **Comments:**

Ok previous to maria actually, no power

### **Access:**

• Safe Access to Buildings: Yes

**Comments:** 

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

#### **Comments:**

#### **Overall Areas:**

- Recreation Area Damage: Moderate
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Moderate
- Debris or Tree Hazards: Moderate
- Electrical or Power Line Hazards: Minor/None

#### **Comments:**

Basketball court due infiltration

#### **Lunch Room:**

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

#### **Comments:**

## **Buildings:**

#### **Comments:**

## **Additional Comments:**

## **Findings:**

Basketball court has moderate infiltration through several inside roof insulation panels. Condition is pre existing. Got worst with Maria

## **Recommendations:**

Isolate baskeball court and start operations as soon as power is available