

Facility Evaluation (Site) Form for: Luis Muñoz Rivera | Código: 71118

Inspector(s) Name:

Jonas Parker

Inspection Date:

Mon Oct 23 2017

Inspection Time:

16:57:09 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Luis Muñoz Rivera

School Code:

71118

Latitude:

18.47443782

Longitude:

-66.26605115

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:Water is intermitent. No Power

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

No known damage to AC

Access:

- Safe Access to Buildings: **Yes**

Comments:**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

No known hazards

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:**Buildings:**

- Building 1: **Green - Inspected**

Comments:

Additional Comments:

Findings:

1. The water service is intermittent.
-

Recommendations:

1. water service is intermittent.
-