

Facility Evaluation (Site) Form for: Luisa M Valderrama (San Antonio) |Codigo: 71134

Inspector(s) Name:

Jonas Parker

Inspection Date:

Mon Oct 23 2017

Inspection Time:

17:05:41 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Luisa M Valderrama (San Antonio)

School Code:

71134

Latitude:

18.44895094

Longitude:

-66.29350685

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **No**

Comments:

Water service yes, but no po5

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

Comments:

No known damage to ac units

Access:

- Safe Access to Buildings: **Yes**

Comments:

Clean

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

One area broken, then fixed

Overall Areas:

- Recreation Area Damage: **Unknown**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Could not access Gymnasium

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Yellow - Restricted Use**

- Building 4: **Green - Inspected**

Comments:

Additional Comments:

Could not access Gymnasium because couldn't find key

Findings:

1. Broken hand rail from the main bldg. second floor.
-

Recommendations:

1. Restrict the walkway on the second floor until it's fixed, the school is in good conditions to open.
-