# Facility Evaluation (Site) Form for: Espinosa Kuilan | Codigo: 71167

## Inspector(s) Name: SJ-07 **Inspection Date:** Mon Oct 23 2017 **Inspection Time:** 07:36:47 GMT-0500 (Central Daylight Time) Type of Facility: comm\_shelter **School Name:** Espinosa Kuilan **School Code:** 71167 Latitude: 18.40331348 Longitude: -66.30073705 **Building Contact:**

#### **General:**

• Facility Area Flooded: No

One or More Buildings Flooded: No

• Other Water Damage in Facility: No

### **Comments:**

**Number of Buildings:** 

#### **Services:**

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: No

Septic Tank Available: Yes

Electrical Power Service: No

• Generator Available: No

Gas (LP) Storage Tank Intact: Yes

#### **Comments:**

The 2 cisterns are broken.

### **Class Room Ventilation:**

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

#### **Comments:**

#### Access:

• Safe Access to Buildings: Yes

#### **Comments:**

## **Perimeter Fences/Walls:**

• Damage to Perimeter or Fence: Minor/None

• Damage to Retaining Wall or Slope: Minor/None

#### **Comments:**

Some debris and trees in the perimeter of the school. The entrance of the school and parking are clear.

#### **Overall Areas:**

• Recreation Area Damage: Minor/None

• Parking Area Damage: Minor/None

• Falling Hazards in Play Areas: Minor/None

• Standing Water in Play Areas: Minor/None

• Debris or Tree Hazards: Moderate

• Electrical or Power Line Hazards: Minor/None

#### **Comments:**

#### **Lunch Room:**

• Cooking Equipment: Yes

• Refrigerated or Dry Food Storage: No

• Operational Exhaust Fan: No

• Fire Suppression System: No

• Screens: Yes

#### **Comments:**

## **Buildings:**

- Building 1: Green Inspected
- Building 2: Green Inspected

#### **Comments:**

Building 1: office and classrooms, 2 floors; Building 2: office, classrooms and lunch room. The school function as a shelter; now they don't have any refugee.

## **Additional Comments:**

## Findings:

1. No water service. 2. Debris in many areas of the school. 3. Fallen trees damaged some parts of the perimeter fence.

## **Recommendations:**

1. Barricade areas with debris until they are removed. 2. Barricade areas where there are fallen trees until perimeter fence is repaired.