

# Facility Evaluation (Site) Form for: Jose Gualberto Padilla |Codigo: 71860

---

**Inspector(s) Name:**

SJ-11

**Inspection Date:**

Mon Oct 30 2017

**Inspection Time:**

09:24:50 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Jose Gualberto Padilla

**School Code:**

71860

**Latitude:**

18.44573301

**Longitude:**

-66.3899163

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Ceiling water infiltration.

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Moderate**

**Comments:**

Remove tree branches loosened. Fix light fixtures hanging from the wing slab. Communication and electrical cables down.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

---

**Buildings:**

- Building 1: **Yellow - Restricted Use**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Yellow - Restricted Use**

- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**

**Comments:**

---

**Additional Comments:**

---

**Findings:** Hanging tree branches. Light fixtures hanging from the wing slab. Communication and electrical cables down. Moderate damage to perimeter fence.

---

**Recommendations:** Remove hanging tree branches. Fix light fixtures hanging from the wing slab. Remove/repair downed communication and electrical cables. Repair perimeter fence.

---