Facility Evaluation (Site) Form for: Angel Sandin Martinez | Codigo: 71886

Inspector(s) Name:
Inspection Date:
Mon Oct 23 2017
Inspection Time:
08:30:00 GMT-0500 (Central Daylight Time)
Type of Facility:
escuela
School Name:
Angel Sandin Martinez
School Code:
71886
Latitude:
18.44348369
Longitude:
-66.38411211
Building Contact:
Number of Buildings:

General:

• Facility Area Flooded: No

• One or More Buildings Flooded: No

• Other Water Damage in Facility: No

Comments:

Services:

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: No

Septic Tank Available: YesElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

• Adequate Classroom Ventilation: Yes

AC System Operating: No
Comments:
Access:
Safe Access to Buildings: Yes
Comments:
Perimeter Fences/Walls:
Damage to Perimeter or Fence: Minor/None
Damage to Retaining Wall or Slope: Minor/None
Comments:
Overall Areas:
Recreation Area Damage: Minor/None
Parking Area Damage: Minor/None
Falling Hazards in Play Areas: Minor/None
Standing Water in Play Areas: Minor/None
Debris or Tree Hazards: Minor/None
Electrical or Power Line Hazards: Moderate
Comments:
Main breaker damage,
Lunch Room:
Cooking Equipment: Yes
Refrigerated or Dry Food Storage: Yes
Operational Exhaust Fan: Yes
Fire Suppression System: Yes
• Screens: Yes
Comments:
Buildings:
Comments:
Additional Comments:
Additional Comments:

Findings:

1. Main breaker broken 2. There are broken windows in the main bldg, the second bldg. and special education classroom

Recommendations:

1. Barricade and repair the main breaker. Cover the area where the windows are broken ans replace them.