

Facility Evaluation (Site) Form for: Su Almirante Norte | Codigo: 72090

Inspector(s) Name:**Inspection Date:**

Sun Oct 22 2017

Inspection Time:

23:30:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Su Almirante Norte

School Code:

72090

Latitude:

18.40907459

Longitude:

-66.36775994

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

The cistern is not operational

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Moderate**

Comments:

The roof over the bleachers has severe damage. There is debris in common areas. Some cables are hanging between the buildings.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1. Vocational education wooden roof was destructed. 2. Water cistern tank has a broken valve. 3. There are hanging cables between the library building and middle school building. 4. The garden drainage was covered with mud. 5. Some tree branches were in the middle of the walkways and roof parapets 6. A falling tree broke a window in the main building 7. The metal roof of the basketball court bleachers area was destructed.

Recommendations:

1. Reconstruct with wood planks and panels. 2. Replace water cistern tank valve. 3. Re-wire cables and attach it to the roof parapet. 4. Clean the drainage to prevent more flooded areas and clean the surroundings too. 5. Remove the branches from those spaces. 6. Replace the broken window in the main building with a new one. 7. Barricade basketball court until new metal sheets are installed.
