Facility Evaluation (Site) Form for: Agapito Rosario Rosario | Codigo: 74807

Inspector(s) Name:

Group 10, Ronhny Frias, Ethel Rivera, Angel Rodriguez

Inspection Date:

Mon Oct 23 2017

Inspection Time:

10:00:15 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Agapito Rosario Rosario

School Code:

74807

Latitude:

18.43419377

Longitude:

-66.40216647

Building Contact:

Number of Buildings:

General:

• Facility Area Flooded: No

• One or More Buildings Flooded: No

• Other Water Damage in Facility: No

Comments:

Services:

• Potable Water Service: Yes

• Potable Water Cistern: Yes

• Sewer Service: Yes

Septic Tank Available: No

• Electrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Cisterns not working

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

• Damage to Perimeter or Fence: Minor/None

• Damage to Retaining Wall or Slope: Minor/None

Comments:

Parking lot and back gates broken

Overall Areas:

• Recreation Area Damage: Minor/None

• Parking Area Damage: Minor/None

• Falling Hazards in Play Areas: Minor/None

• Standing Water in Play Areas: Minor/None

• Debris or Tree Hazards: Moderate

• Electrical or Power Line Hazards: Minor/None

Comments:

A pair of exterior lighting fixtures hanging.

Lunch Room:

• Cooking Equipment: Yes

• Refrigerated or Dry Food Storage: Yes

Operational Exhaust Fan: Yes

• Fire Suppression System: Yes

• Screens: Yes

Comments:

Buildings:

• Building 1: Green - Inspected

• Building 2: Green - Inspected

Comments:

Building 1 = all areas, building 2= therapy

Additional Comments:

Findings:

1. The bldg. was flooded but not significant. 2. Has cistern but not available. Not working. 3. Hanging lights features.

Recommendations:

1. Needs water service. 2. Remove hanging light fixtures.