

Facility Evaluation (Site) Form for: Ileana De Gracia (Superior Nueva) |Codigo: 79038

Inspector(s) Name:

Lebron & Castro

Inspection Date:

Mon Oct 30 2017

Inspection Time:

07:30:40 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Ileana De Gracia (Superior Nueva)

School Code:

79038

Latitude:

18.41993203

Longitude:

-66.33514251

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

The teachers parking is partially flooded with storm water runoff.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Water filtrates through PVC conduit wall penetration that feeds electrical panel in room at north east corner in first floor.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Downed transmission line at exit to PR #2

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Bent segment of fence.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Hanging communications cables on the interior patio.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Some screens mesh are broken, but the kitchen administrator all ready reported.

Buildings:

Comments:

Additional Comments:

In marginal road outside the school sanitary manhole is overflowing.

Findings:

School facility electrical power is distributed by underground conduits. There is no risk of getting in contact from fallen electrical with wires inside school.

Recommendations:

School facility has no safety hazard, therefore we designate on overall rating of green.
