Facility Evaluation (Site) Form for: Esperanza Gonzalez | Codigo: 12260

Inspector(s) Name:

Sebastian Morales, , , **Inspection Date:** Thu Oct 19 2017 **Inspection Time:** 06:26:00 GMT-0500 (Central Daylight Time) **Type of Facility: School Name:** Esperanza Gonzalez **School Code:** 12260 Latitude: 18.30800139 Longitude: -66.39330777 **Building Contact:** Number of Buildings:

General:

- Facility Area Flooded: No
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Services:

- Potable Water Service: No
- Potable Water Cistern: Yes
- Sewer Service: Yes
- Septic Tank Available: No
- Electrical Power Service: No
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

• Adequate Classroom Ventilation: Yes

• AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Severe
- Damage to Retaining Wall or Slope: Moderate

Comments:

70% partially collapsed by trees

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

Comments:

Barricade at basketball court

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: No
- Operational Exhaust Fan: Yes
- Fire Suppression System: No
- Screens: Yes

Comments:

Buildings:

- Building 1: Green Inspected
- Building 2: Green Inspected
- Building 3: Green Inspected
- Building 4: Green Inspected
- Building 5: Green Inspected
- Building 6: Green Inspected

- Building 7: Green Inspected
- Building 8: Green Inspected

Comments:

Additional Comments:

Findings:

1. Severe damages to perimeter fence (70% of the fence collapse by trees).

Recommendations:

1. Barricade damaged fencevarea until is repaired. 2. Barricade at the basketball court.