Facility Evaluation (Site) Form for: Juana M. Aviles | Codigo: 12278

Inspector(s) Name:

Sebastian Morales, , ,

Inspection Date:

Thu Oct 19 2017

Inspection Time:

03:37:00 GMT-0500 (Central Daylight Time)

Type of Facility:

School Name:

Juana M. Aviles

School Code:

12278

Latitude:

18.35627009

Longitude:

-66.40964709

Building Contact:

Number of Buildings:

General:

- Facility Area Flooded: Yes
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Central patio is flooded.

Services:

- Potable Water Service: Yes
- Potable Water Cistern: No
- Sewer Service: Yes
- Septic Tank Available: No
- Electrical Power Service: No Data
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

Need power to operate cistern pumps. Generator was bandalized and AEP is working to repair it.

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Moderate
- Damage to Retaining Wall or Slope: Moderate

Comments:

Overall Areas:

- Recreation Area Damage: Moderate
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Moderate
- Electrical or Power Line Hazards: Minor/None

Comments:

Lunch Room:

- Cooking Equipment: No Data
- Refrigerated or Dry Food Storage: No
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

Comments:

Buildings:

- Building 1: Green Inspected
- Building 2: Green Inspected

Comments:

Additional Comments:

Findings:

1. Flooded inner patio. 2. No power for cisterns pump. 3. Vandalized power generator. 4. Hazards behind the building and in front of the basketball court. 5. Leaning tree against parapet in building 3.

Recommendations:

1. Barricade behind building in play areas. 2. Barricade access ramp to basketball court.