

Facility Evaluation (Site) Form for: Su David Colon Vega |Codigo: 12419

Inspector(s) Name:

Inspection Date:

Thu Oct 19 2017

Inspection Time:

06:40:00 GMT-0500 (Central Daylight Time)

Type of Facility:

School Name:

Su David Colon Vega

School Code:

12419

Latitude:

18.30404063

Longitude:

-66.41491724

Building Contact:

Number of Buildings:

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

TWO CLASSROOMS

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**

- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

SEVERAL

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No Data**
- Screens: **No Data**

Comments:

DAMAGED /DE

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**

- Building 7: **Green - Inspected**
- Building 8: **Red - Unsafe**
- Building 9: **Red - Unsafe**
- Building 10: **Green - Inspected**

Comments:

Additional Comments:

Findings:

1. Two classrooms are flooded. 2. Several fallen power lines. 3. Damaged Lunch Room exhaust fan 4. Debris found in several places. 5. Damage to perimeter fence and other fences around campus 6. Damaged water cistern 7. Several broken planters 8. Broken handrail 9. Bldg 9: Broken window; metal roof canopy damaged (unsafe); roof water leaks, mud in 1st floor entrance; damaged and exposed electrical panel; flooded rooms 10. A/C unit on window is falling and lamp on ceiling is hanging in Bldg 1. 11. Bldg 3: Loose cement ceiling plaster 12. Bldg 4: Damaged window louvers 13. Bldg 10: Damaged window louvers; dangerous access 14. Bldg 12: Window louver broken; minor water leakage 15. Bldg 11: roof damage; stair damage

Recommendations:

1. clean the Two classrooms flooded. 2. clean the power lines. 3. fix Lunch Room exhaust fan 4. clean debris in several places. 5. fix or barricade the perimeter fence and around campus 6. fix water cistern 7. clean broken planters 8. fix or barricade handrail 9. Bldg 9: fix or barricade 10. fix the A/C unit and lamp on ceiling hanging in Bldg 1. 11. Bldg 3: fix cement ceiling plaster 12. Bldg 4: fix window louvers 13. Bldg 10: barricade dangerous access 14. Bldg 12: fix and roof treatment 15. Bldg 11: fix and roof treatment
