

# Facility Evaluation (Site) Form for: Barahona Elemental |Codigo: 12435

---

**Inspector(s) Name:**

Yolanda T. Garcia

**Inspection Date:**

Tue Oct 24 2017

**Inspection Time:**

09:00:00 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Barahona Elemental

**School Code:**

12435

**Latitude:**

18.35501614

**Longitude:**

-66.44262089

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Cracks in ceiling. Leaks from upper floor in Administration Building. Waterproofing membrane blown away.

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **Yes**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Water Cisterns not working

---

## Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

### Comments:

---

## Access:

- Safe Access to Buildings: **Yes**

### Comments:

---

## Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

### Comments:

Trees down

---

## Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Moderate**
- Debris or Tree Hazards: **No Data**
- Electrical or Power Line Hazards: **Moderate**

### Comments:

Standing water in walkways. Electrical hazard along walkway and in front of yard along roadway.

---

## Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### Comments:

Exhaust fan is not working.

---

## Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Yellow - Restricted Use**
- Building 8: **Yellow - Restricted Use**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

**Comments:**

Building 1 Estimated Damages 1 to 10%. Barricades at hanging cap flashing area. Building 2 Estimated Damages 100%. Building 3 Estimated Damages 1 to 10%. Barricade Hanging Comm. lines between Bldg 5 and Bldg 3. Building 4 Estimated Damages 0 to 10%. Building 5 estimated damages 1 to 10%. Barricade under power lines on front of the dining wall. Building 6 estimated damages 0 to 1%. Barricade the green area between Bldg 5 and behind the building. Building 7 estimated building damage

---

**Additional Comments:**

Electrical Panels has blank spaces. Electrical cables is hanging from building. Paint is peeling from walls due to storm. Broken window shutters in classrooms. Building 11 has water damaged. Gutter hanging from roof in building 1. Weather head damaged, gutters and weatherproof membrane blown off on building 5. Covered walkway is damaged. Canopy roof is missing. Electrical Panel and receptacle outlet in building 7 have water leaks. Water damaged to four light fixtures.

---

**Findings:**

1. Standing water in walkways. Electrical hazard along walkway and in front of yard along roadway. 3. Building 2 Estimated Damages 100%. 4. Building 3 Estimated Damages 1 to 10%. 5. Hanging Comm. lines between Bldg 5 and Bldg 3. 6. Building 4 Estimated Damages 0 to 10%. 7. Building 5 estimated damages 1 to 10%. 8. Barricade under power lines on front of the dining wall. 9. Building 6 estimated damages 0 to 1%. 10. Barricade the green area between Bldg 5 and behind the building. 11. Building 7 estimated building damage1.

---

**Recommendations:**

1. Barricades area at hanging cap flashing area. 2. bldg #2,3,6,7 barricade 3.bldg #3 fix damage 4.barricade thru bldg 3 and 5 and behind bldg 5

---