

# Facility Evaluation (Site) Form for: Su Bonifacio Alvarado | Codigo: 12518

---

**Inspector(s) Name:**

Richard Allwes, Ashley McDonald, Jesse Agosto

**Inspection Date:**

Tue Oct 24 2017

**Inspection Time:**

13:15:14 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Su Bonifacio Alvarado

**School Code:**

12518

**Latitude:**

18.17450183

**Longitude:**

-66.43287973

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Potable water service not always available.

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

**Comments:**

No power to evaluate the AC units

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Severe**

**Comments:**

Perimeter fence affected some areas around school. Retaining wall severe affected behind bldg. 1

---

**Overall Areas:**

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Severe**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Moderate**

**Comments:**

Parking unavailable due to basketball court collapse. Debris from basketball court. Some secondary (120V) and security light wiring is downed.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

Exhaust fan is broken.

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Red - Unsafe**
- Building 7: **Green - Inspected**
- Building 8: **Red - Unsafe**

**Comments:**

---

**Additional Comments:**

Bldg 5 service entrance is PVC piping and is bending away from bldg, replace w/proper material.

---

**Findings:**

1. Moderate debris, tree ,electrical, power line hazards, 2. parking unavailable due to debris from basketball court collapse. 3. Electrical Panels has blank spaces. Electrical cables is hanging from building. Paint is peeling from walls due to storm, broken window shutters in classrooms. 4. Building 11 has water damaged. 5. Gutter hanging from roof in building 1. 6. Weather head damaged, gutters and weatherproof membrane blown off on building 5. 7. Covered walkway is damaged. Canopy roof is missing. 8. Electrical Panel and receptacle outlet in building 7 have water leaks also damaged four light fixtures.

---

**Recommendations:**

1. Barricade perimeter fence and retaining wall areas until are repaired. 2. Remove debris. 3. Remove hazards from hanging gutters. 4. replaced ligths features.

---