

Facility Evaluation (Site) Form for: Su Sanamuertos |Codigo: 12765

Inspector(s) Name:

James Scungio and violet

Inspection Date:

Tue Oct 24 2017

Inspection Time:

10:00:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Su Sanamuertos

School Code:

12765

Latitude:

18.23946346

Longitude:

-66.40470928

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

infiltration through doors, windows and roof throughout. infiltration through existing mechanical/ electrical penetrations.

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

no existing exhaust fans no fire suppression system.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**

- Building 7: **Yellow - Restricted Use**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

Comments:

Additional Comments:

Building 7 and 8 to be reoccupied by other school. building 7 2nd floor recommended testing of all electrical fixtures prior to reenergizing building circuits. recommend repair of metal roof section North side. recommend all windows to be resealed leaking occurred post hurricane.

Findings:

1. Flooded areas, One or more buildings flooded. 2. Water damage (infiltration through doors, windows and roof, existing mechanical/ electrical penetrations), No water and power services, moderate damage perimeter fence, recreation area. 3. Building 7 and 8 will be shared by other school. 4. building 7 on 2nd floor recommended testing of all electrical fixtures prior to reenergizing building circuits.

Recommendations:

1. Barricade perimeter fence until is Repaired 2. Remove debris. 3. recommend repair of metal roof section north side. 4. all windows to be resealed leaking occurred post hurricane.
