

# Facility Evaluation (Site) Form for: Virgilio Davila |Codigo: 70011

---

**Inspector(s) Name:**

SJ01

**Inspection Date:**

Wed Oct 25 2017

**Inspection Time:**

09:14:43 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Virgilio Davila

**School Code:**

70011

**Latitude:**

18.40554095

**Longitude:**

-66.18801031

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Intermittent water service. No water today. A septic tank is on site but does not work and is only for one bathroom.

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

Main gate damaged. Minor fence damage in the back.

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

Branches broken in tree hanging above play area courtyard.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

Tree debris on roof of Physical Education Building.

---

**Buildings:**

- Building 1: **Yellow - Restricted Use**
- Building 2: **Yellow - Restricted Use**
- Building 3: **Yellow - Restricted Use**
- Building 4: **Yellow - Restricted Use**

- Building 5: **Yellow - Restricted Use**
- Building 6: **Yellow - Restricted Use**
- Building 7: **Yellow - Restricted Use**

**Comments:**

See plan drawing for building designation. Building No.3 has damaged door. Building No.5 has tree debris on the roof.

---

**Additional Comments:**

---

**Findings:**

1. Intermittent water service. No water today. 2. A septic tank is on site but does not work and is only for one bathroom. 3. See plan drawing for building designation. Building No.3 has damaged door. Building No.5 has tree debris on the roof. 4. Branches broken in tree hanging above play area courtyard. 5. Tree debris on roof of Physical Education Building

---

**Recommendations:**

1. need water services 2.fix bathroom needs 3.bldg3 fix door 4. bldg 5 clean debris on top of the roof 5. bldg of PE clean debris on roof.

---