

Facility Evaluation (Site) Form for: Dr. Santos J. Sepulveda |Codigo: 70037

Inspector(s) Name:

SJ-04

Inspection Date:

Mon Oct 23 2017

Inspection Time:

09:45:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Dr. Santos J. Sepulveda

School Code:

70037

Latitude:

18.40227303

Longitude:

-66.17386401

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

Leaks from ceiling. Water Cistern plumbing lines cut.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Substation intact

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **No**

Comments:

Leaning power pole near entrance

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Moderate**

Comments:

Wall damaged by trees

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Communication cables in walkways

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

No power

Buildings:

- Building 1: **Green - Inspected**

- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**

Comments:

Barricade Kinder playground area. Kinder building remove branches from roof top. Barricade the backside of Terrace due to debris. Minor damage to steel panel due to fallen tree

Additional Comments:

Fence damaged near canopy. Tree limbs on kindergarden roof. Water leaks through conduit room S.01.1201. Electrical Conduit hanging from main building.

Findings:

1. Damaged fences 2. Downed trees and debris around campus 3. Main Building: Communication and electric cables are hanging on top of the building 4. Leaking ceilings in main building in classrooms S-011201, kindergarden building, terrace 2 5. Minor damage to steel panel due to a fallen tree on roof in Terrace 1

Recommendations:

1. Put up barricades around downed fence and downed trees 2. Remove tree branches from the top of the kindergarden building 3. Repair the electrical conduits and relocate students from main building until it is repaired 4. Repair cables that are hanging 5. Repair damaged steel panel in Terrace 1 6. Tarp roofs and/or repair roofs 7. Repair damaged ceiling
