

Facility Evaluation (Site) Form for: Epifanio Fernandez Vanga |Codigo: 70144

Inspector(s) Name:

SJ01

Inspection Date:

Wed Oct 25 2017

Inspection Time:

10:46:38 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Epifanio Fernandez Vanga

School Code:

70144

Latitude:

18.38907485

Longitude:

-66.17891274

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

The roof membrane of the main school building has been completely destroyed and removed.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Tree knocked down part of the chain link fence.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Moderate**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Severe**

Comments:

Standing water in courtyard and gazebo. Debris of piled tree branches and roof membrane in courtyard.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

The exhaust fan outlet was destroyed.

Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Yellow - Restricted Use**
- Building 3: **Red - Unsafe**

Comments:

Building No. 1: main school building; Building No. 2: Annex classrooms; Building No. 3: Electrical Building

Additional Comments:**Findings:**

1. debris around the area 2. leak from ceiling 3. perimeter fence collapse

Recommendations:

1. clean debris around the area 2. fix roof membrane 3. fix perimeter fence
