Facility Evaluation (Site) Form for: Rexville Elemental | Codigo: 70243

Inspector(s) Name:
SJ-11
Inspection Date:
Fri Oct 27 2017
Inspection Time:
08:15:44 GMT-0500 (Central Daylight Time)
Type of Facility:
escuela
School Name:
Rexville Elemental
School Code:
70243
Latitude:
18.37114349
Longitude:
-66.19044334
Building Contact:
Number of Buildings:
General:
Facility Area Flooded: No
One or More Buildings Flooded: No
Other Water Damage in Facility: No

Services:

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: **Yes**

Comments:

• Septic Tank Available: **No**

• Electrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

• Damage to Perimeter or Fence: Minor/None

• Damage to Retaining Wall or Slope: Minor/None

Comments:

On rear yard section torn down

Overall Areas:

• Recreation Area Damage: Minor/None

• Parking Area Damage: Minor/None

• Falling Hazards in Play Areas: Minor/None

Standing Water in Play Areas: Minor/None

• Debris or Tree Hazards: Minor/None

• Electrical or Power Line Hazards: Minor/None

Comments:

Lunch Room:

• Cooking Equipment: Yes

• Refrigerated or Dry Food Storage: Yes

• Operational Exhaust Fan: Yes

• Fire Suppression System: Yes

• Screens: Yes

Comments:

Buildings:

- Building 1: Green Inspected
- Building 2: Yellow Restricted Use
- Building 3: Green Inspected
- Building 4: Green Inspected
- Building 5: Green Inspected
- Building 6: Green Inspected

Bldg 3 side of wall blown off.	. Window smash.		
Additional Comments	:		

Findings:

1. Moderate damages to fence (on rear yard section torn down) 2. Bldg 3 side of wall blown off. Window smash.

Recommendations:

Comments:

1. Barricade damaged fence area unit is repaired. 2. Restrict the use of affected areas of building 3, until is repaired