

Facility Evaluation (Site) Form for: Miguel Melendez Muñoz | Código: 70276

Inspector(s) Name:

SJ-05

Inspection Date:

Mon Oct 23 2017

Inspection Time:

19:30:39 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Miguel Melendez Muñoz

School Code:

70276

Latitude:

18.36988296

Longitude:

-66.17736886

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Utility pole knocked near entrance

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Most debris is limited to one area; there's also one conduit encase power line that drop and it's near ramp and other comm lines.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Unknown**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Exhaust fan was damaged , can potentially be re-installed

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**

- Building 5: **Green - Inspected**
- Building 6: **Red - Unsafe**

Comments:

See overall plan for building description

Additional Comments:

Findings:

1. Water infiltration from ceiling in classrooms and cafeteria 2. Lunchroom exhaust fan damaged 3. Special Education - Building 6 is unsafe. 4. Structural damages to the gazebo. 5. Physical Education classroom perimeter lights damaged 6. Debris (trees) around the area.

Recommendations:

1. Restrict the use of building 6, physical education and the gazebo. 2. Barricade or remove the debris area.
