

Facility Evaluation (Site) Form for: Su Cacique Majagua |Codigo: 70334

Inspector(s) Name:

SJ-05

Inspection Date:

Tue Oct 24 2017

Inspection Time:

14:00:53 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Su Cacique Majagua

School Code:

70334

Latitude:

18.32942452

Longitude:

-66.18732788

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Flooding limited two one classroom

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Moderate**

Comments:

Lots of damage to fence around perimeter due to trees laying

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

There a couple low laying wires that need to be coiled and stored

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1.Moderate damage to perimeter fence. 2.Downed power lines.

Recommendations:

1.Fix perimeter fence and power line. 2.Remove gutter from entrance of court.
