

Facility Evaluation (Site) Form for: Maria Vazquez Umpierre |Codigo: 70367

Inspector(s) Name:

Jonas Parker

Inspection Date:

Wed Oct 25 2017

Inspection Time:

09:15:32 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Maria Vazquez Umpierre

School Code:

70367

Latitude:

18.34335193

Longitude:

-66.19604014

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

Some leaking in a few rooms on the second floor. Recommended to check roof and AC units once more.

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Power pole broken in half

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

No one has looked on the roof (ac units)

Access:

- Safe Access to Buildings: **Yes**

Comments:

Roofing and AC units need further inspection

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Electric power pole feeding the school is broken in half.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **No Data**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

Comments:

Additional Comments:

Some leaking in a few rooms on the second floor. Recommended to check roof and AC units once more

Findings:

1. Minor interior leak 2. Water leaking in light fixtures

Recommendations:

1. roof treatment 2. fix leaking in light fixtures
