

# Facility Evaluation (Site) Form for: Bernardo Huyke |Codigo: 70409

---

**Inspector(s) Name:**

Marcus Ramos, Heriberto Morales

**Inspection Date:**

Mon Oct 30 2017

**Inspection Time:**

11:10:00 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Bernardo Huyke

**School Code:**

70409

**Latitude:**

18.35862235

**Longitude:**

-66.16106441

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Cisterns fell from roof.

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

Majority of rear fence partially collapsed.

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

Suspended UF power line at rear of kindergarten.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

Lunch room do not have exhaust fan.

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

**Comments:**

Building #2 has water leak due to missing roof membrane.

---

**Additional Comments:**

---

**Findings:**

Water cisterns have fallen from roof. Majority of the rear perimeter fence has partially collapsed. UF power line suspended at the back of kindergarten building.

---

**Recommendations:**

Water cisterns have to be mounted or replaced with new ones. The rear perimeter fence is placed on top of a concrete wall (about 7ft) fence there's no need for a barricade. Electrical power need to be in original place. Electrician evaluation is needed.

---