

Facility Evaluation (Site) Form for: Angel Mislan Huertas |Codigo: 70466

Inspector(s) Name:

Jonas Parker

Inspection Date:

Fri Oct 27 2017

Inspection Time:

09:11:21 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Angel Mislan Huertas

School Code:

70466

Latitude:

18.3529384

Longitude:

-66.1515918

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **Unknown**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

3 AC condensers displaced

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **No Data**

Comments:

40 foot section down in back by play area

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Play area fence is being fixed today

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Unknown**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

Comments:

Additional Comments:

Findings:

1.Fence and electric panel damaged in kindergarten play area. The school don't have power.

Recommendations:

1.Fix fence and electric panel at play area. Electrician evaluation is recommended.
