

Facility Evaluation (Site) Form for: Jose Campeche |Codigo: 70482

Inspector(s) Name:

Jonas Parker

Inspection Date:

Fri Oct 27 2017

Inspection Time:

06:31:15 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Jose Campeche

School Code:

70482

Latitude:

18.35129573

Longitude:

-66.16032243

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Intermittent water**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **Unknown**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Cisterns and piping ok but the cisterns need to go back up on the roof.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Unknown**

Comments:

No known damage to ac units.

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **No Data**

Comments:

Front gate broken

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Severe**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Hanging broken tree limb in play area. Falling hazard.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **No Data**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

Comments:

Additional Comments:

Findings:

1. Cisterns and piping look ok, but not operating. 2. Minor damages to the fence (Front gate broken) 3. Hanging broken tree limb in play area. Falling hazard.

Recommendations:

1. The cistern need to be evaluated. 2. Remove debris. 3. fix perimeter fence.
