

Facility Evaluation (Site) Form for: Dr. Jose Padin |Codigo: 70565

Inspector(s) Name:

Inspection Date:

Thu Oct 19 2017

Inspection Time:

09:20:00 GMT-0500 (Central Daylight Time)

Type of Facility:

School Name:

Dr. Jose Padin

School Code:

70565

Latitude:

18.37330621

Longitude:

-66.15303951

Building Contact:

Number of Buildings:

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

water infiltration in some classrooms (minor). Other through windows.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**

- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Moderate**

Comments:

Rec area: debris; parking area: debris; fall hazards: debris.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1. Debris hazard 2. Interior water leaks 3. Tree on roof 4. Exhaust fan on ground

Recommendations:

1. removed debris hazard 2. roof treatment 3. removed tree on roof 4. fix exhaust fan
