

Facility Evaluation (Site) Form for: Andres C. Gonzalez |Codigo: 70672

Inspector(s) Name:

SJ-07

Inspection Date:

Mon Oct 30 2017

Inspection Time:

07:51:42 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Andres C. Gonzalez

School Code:

70672

Latitude:

18.31523012

Longitude:

-66.16490274

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

The generator needs to be inspected and repair.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Unknown**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**

Comments:

Additional Comments:

Findings:

In the back of the school have 2 broke windows.

Recommendations:

The generator needs to be repair. And 2 windows in the back of the school need to be repair.
