

Facility Evaluation (Site) Form for: Isaac Del Rosario |Codigo: 70755

Inspector(s) Name:

Richard Allwes, Ashley McDonald, Jesse Agosto

Inspection Date:

Mon Oct 30 2017

Inspection Time:

14:15:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Isaac Del Rosario

School Code:

70755

Latitude:

18.42982325

Longitude:

-66.14378446

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

No power to evaluate / 1 AC unit damaged

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Severe**

Comments:

Trees damaged perimeter fence and retaining wall

Overall Areas:

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Trees down (supposed to be removed on October 31, 2017)

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

No power to evaluate refrigerators. Exhaust fan does not work.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Yellow - Restricted Use**

- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**
- Building 9: **Yellow - Restricted Use**

Comments:

Additional Comments:

Internet cable and some conduct and metal framed box need to be removed.

Findings:

The bleacher area damage by impact. Water fountain in first floor is damaged. Debris debris around the school. The school don't have power.

Recommendations:

Barricade bleacher area damage by impact. Barricade area about 1st floor water fountain. Remove all debris around the school. Electrician evaluation is recommended.
