

# Facility Evaluation (Site) Form for: Francisco Oller |Codigo: 70813

---

**Inspector(s) Name:**

Raiza Rivera

**Inspection Date:**

Tue Oct 31 2017

**Inspection Time:**

09:00:48 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Francisco Oller

**School Code:**

70813

**Latitude:**

18.44180011

**Longitude:**

-66.12811344

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

None

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Potable water have a pumps, but there is no power. Cistern does not work because there is no power. There is a generator, but does not work. Generator need to be fixed as son as possible.

---

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

### **Comments:**

A/C chiller do not work. And there is no power.

---

## **Access:**

- Safe Access to Buildings: **Yes**

### **Comments:**

---

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

### **Comments:**

Back yard fence is completely broken, but is already under construction. Also, there is a minor damage in a perimeter concrete wall

---

## **Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

### **Comments:**

Branches on tree need to be removed in front of the school. In same place there is a side walk that is broken because a falling tree. These area need to be barricade until branches can be removed and sidewalk can be fixed; Exterior wall plaster fell down in interior garden. Barricade area around wall until it can be repaired.

---

## **Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### **Comments:**

One freezer and one refrigerator had damaged. Mechanical evaluation is required.

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

**Comments:**

---

**Additional Comments:**

---

**Findings:**

Potable water have a pumps, but there is no power. Cistern does not work because there is no power. There is a generator, but does not work; Branches on trees need to be removed at front part of the school. In same place there is a side walk that is broken because a falling tree; Exterior wall plaster fell down in interior garden. Data cables fell down in front of the school.

---

**Recommendations:**

Generator need to be fixed as son as possible. School just need portable water to star class and is necessary give power to cistern pump; Front part of the school need to be barricade until branches and tree debris can be removed, and sidewalk can be re built. Barricade area around wall in interior garden until it can be repaired; Date cables need to be relocated in original place.

---