

# Facility Evaluation (Site) Form for: Emilio R. Delgado |Codigo: 70888

---

**Inspector(s) Name:**

SJ:04

**Inspection Date:**

Wed Oct 25 2017

**Inspection Time:**

10:30:52 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Emilio R. Delgado

**School Code:**

70888

**Latitude:**

18.34035054

**Longitude:**

-66.32189469

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

**Comments:**

Building L-101

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Electric Service is intact

---

## Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

### Comments:

AC units are damaged

---

## Access:

- Safe Access to Buildings: **Yes**

### Comments:

It's ok

---

## Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

### Comments:

It's knocked down.

---

## Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

### Comments:

Hanging tree limbs, mold in walkways, metal panel hanging from the power lines, electric lines in walkway.

---

## Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### Comments:

The walls from the storage room have moderate leaks.

---

## Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Yellow - Restricted Use**
- Building 3: **Yellow - Restricted Use**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Red - Unsafe**
- Building 9: **Yellow - Restricted Use**
- Building 10: **Green - Inspected**

**Comments:**

The buildings need a re-inspection of a structure engineer. There's mold in more than one building. There's power lines that on the ground around the building. The roof protection blew off by the strong wind and know there are more leaks.

---

**Additional Comments:**

---

**Findings:**

1. The buildings need a re-inspection of a structure engineer. 2. There's mold in more than one building. 3. There's power lines that are on the ground around the building. 4. The roof protection blew off by the strong wind and know there are more leaks. 5. The walls from the storage room have moderate leaks. 6. Hanging tree limbs, mold in walkways, metal panel hanging from the power lines, electric lines in walkway.

---

**Recommendations:**

1. bldg need re inspection of structure engineer 2.clean or barricade the areas with mold 3.clean the power lines around the bldg 4. roof treatment 5.cleared or barricade the walkway.

---