

# Facility Evaluation (Site) Form for: Mercedes Rosado |Codigo: 71217

---

**Inspector(s) Name:**

SJ-05

**Inspection Date:**

Tue Oct 24 2017

**Inspection Time:**

08:00:46 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Mercedes Rosado

**School Code:**

71217

**Latitude:**

18.30156263

**Longitude:**

-66.249052

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

**Comments:**

P.E building and building C flooded due to river rising, since the water level has changed due to the storm. Flooding can happen again

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Cistern requires electricity to operate it does not operate via gravity. Generator needs repairs currently the radiator is broken

---

## Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

### Comments:

---

## Access:

- Safe Access to Buildings: **Yes**

### Comments:

---

## Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Moderate**

### Comments:

Extended damage to chain link fence and terrain due to river water rising

---

## Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

### Comments:

Power line on the ground near parking

---

## Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### Comments:

Faculty filed an OSHA complaint prior to storm due to temperatures in cafeteria reaching over 100 degrees

---

## Buildings:

### Comments:

---

**Additional Comments:**

---

**Findings:**

1.No potable water service available, 2.No electrical power service available, 3.Severe damage to perimeter fence, 4.Power lines on the ground, 5.Missing handrail.

---

**Recommendations:**

1.Provide potable water service, 2.Provide electrical power, 3.Replace perimeter fence. 4. fix, clean or barricade the area of the hand rail.

---