

# Facility Evaluation (Site) Form for: Francisco Morales |Codigo: 71225

---

**Inspector(s) Name:**

SJ-05

**Inspection Date:**

Tue Oct 24 2017

**Inspection Time:**

11:00:42 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Francisco Morales

**School Code:**

71225

**Latitude:**

18.29940093

**Longitude:**

-66.24913679

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Water intermittent ; cistern is available but does not operate

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

There an electrical power line laying across from the school entrance.

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Moderate**

**Comments:**

Lots of erosion , area has never been fenced before , most areas that were fenced before have wind damage

---

**Overall Areas:**

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Moderate**

**Comments:**

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

**Comments:**

---

**Buildings:**

**Comments:**

---

**Additional Comments:**

---

**Findings:**

1.No water service. 2.Moderate damage to perimeter fence. 3.Downed power lines at music building. 4.Main building: large section of louvers missing.

---

**Recommendations:**

1.Fix perimeter fence. 2.Barricade needed in main building. 3.Remove powerlines from music building.

---