

Facility Evaluation (Site) Form for: Bernalda Robles De Hevia |Codigo: 71290

Inspector(s) Name:

Marcus Ramos, Heriberto Morales

Inspection Date:

Mon Oct 30 2017

Inspection Time:

09:41:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Bernalda Robles De Hevia

School Code:

71290

Latitude:

18.2942775

Longitude:

-66.21183099

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Parts of perimeter fence partially collapsed.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Severe**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Moderate**

Comments:

Suspended heavy tree branch at rear of school. Fallen power line in front of school entrance.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Cooler wasn't working before hurricane. Metal window at the back of lunch room damaged.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**

Comments:

Barricades are needed for the fence a the back of the school since there's falling hazard behind the school.

Additional Comments:**Findings:**

Parts of the perimeter fence are partially collapsed. Barricades will be needed for the ones in the rear of the school since they pose a falling hazard due to the elevation of the backyard. There is a suspended heavy tree branch that poses a falling hazard a the rear of the school. Fallen power line in front of the school poses safety hazard. The school don't have power.

Recommendations:

Suspended tree branch must be removed. Fallen power line must be removed o a safe place. Barricades will be needed for the ones in the rear of the school. Electrician evaluation is recommended.
